

Technical Bulletin

SCUFF MARKS

Issued: September, 2018

Revision: March, 2022

Scuff marks do occur occasionally on the surface of concrete roof tile products as a result of normal shipping and handling.

These marks are typically caused by a disturbance to the factory applied sealer, and will dissipate in time as the sealer ages through normal weather cycles. These temporary marks do not compromise the integrity of the base color nor are there any structural implications.